




HEATING REPORT WOOD BURNING SYSTEMS



Heating Report For Wood Burning System				Service Certificate #		# 716	
Location of Risk: 3 Sackitt Road, Fenelon Falls ON				Name of Insured: Deryl Roper			
Broker:				Policy#			
Was the original chimney installed by a certified contractor? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Chimney Type: 7" Excel		S.S Liner Required? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Thimble : <input type="checkbox"/> Wall <input checked="" type="checkbox"/> Ceiling <input type="checkbox"/> N/A	
				S.S Liner Installed? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Thimble Required? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Contractor Name: Fire or ice		Date of Installation: May 7th 2022		Is the unit certified by an approved testing authority? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Make & Age of Unit: Olsen Inferno	
Specific Type of Unit: <input type="checkbox"/> Insert <input type="checkbox"/> Zero Clearance <input type="checkbox"/> Pellet <input checked="" type="checkbox"/> Free Standing <input type="checkbox"/> Masonry <input type="checkbox"/> Furnace		Date of last chimney cleaning: N/A		Special Shielding Required? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Concealed Spaces? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Inspection Done By: Gary Morgan		Inspection Date: May 7th 2022		WETT Certification #: 5923		Ceiling Height Correct? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Phone: 705 878 4074		Fax: 705 738 9021		eMail: fireoricestore@live.ca		Level 1 Inspection Fee \$145.00	
						Level 2 Inspection Fee	
						Level 3 Inspection Fee	
						HST \$18.85	
						TOTAL \$163.85	

The information gathered (upon the level of inspection performed) is based on the measurements and evaluations made on the specific date of this form. All calculations and verifications are based on a experienced assessment. Any visible contravention of the CAN/CSA B365 standard were noted on this date. This report does not claim to have discovered and named every situation, defect, hazard that would cover single eventuality. Also be advised that the Level 1 inspection does not include areas not visible at the time of inspection.

X..... acceptance of requiring party



Special Requirements?	<input checked="" type="checkbox"/> NO	Re-Inspect Required?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Passed?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Level 1 - Readily Accessible: Quickly or easily reached for inspection. Ladders or special tools for opening or removing doors or coverings are not required. Minimum tools required, : tape measure, light, mirror, hammer, camera, magnifying glass and binoculars.					
Level 2 - Accessible: The ability to reach for the purpose of inspection, evaluation, maintenance or repair. Removal of panels/doors or other covering may be required as well as the use of a ladder. Common service/maintenance tools such as a screwdriver, wrench or hammer may also be required. No invasive action to the building or property will be required					
Level 3 - Concealed Accessibility : Accessible only by invasive means. The removal of constructed (not structural) Areas of the system or building may be required to gain access for the purpose of inspection/evaluation. Specialty tools and equipment such as video scanning devises or flue tile removal system may also be required.					