

HALIBURTON, KAWARTHA, PINE RIDGE DISTRICT HEALTH UNIT

SEWAGE SYSTEM INSPECTION REPORT AND USE PERMIT

BX-6-82

FILE NUMBER


REPORT

INSTALLED BY: D. WIRES

DATE: June 9/83

Work authorized by certificate of approval has been satisfactorily completed and includes:

- A. Septic Tank/Holding Tank of working capacity of 4500 litres constructed of steel/concrete/fiberglass on site or prefabricated to serve 3 bedrooms
- B. Distribution Pipe: Type - PVC , Clay Tile , Other _____; Absorption Trench System ; Filter Bed System ; Total 60 Lineal Meters in 4 runs of 15 m and fed by gravity ; Syphon or Pump
- C. Other Details _____

Actual location and orientation of components of sewage system are as shown hereunder or as outlined on the Certificate of Approval form 

SCALE: 1 square equals approx. _____ metres

The following work remains to be completed: Backfill system and sod or seed ; Stabilize all sloped surfaces ; Finish grading to shed run-off and divert water around leaching bed ; Other _____

USE PERMIT

Under section 67 of the Environmental Protection Act, 1980 and regulations and subject to the limitations thereof, a permit is hereby issued to

F. JEFFREY

for the use and operation of the Class 4 Sewage System Installed/Altered under Certificate of Approval # BX-6-82such system being located on Lot 8 Conc. 475 Sub. lot 56Township/Municipality BEXLEY County VICTORIAInspected and Recommended by G. BloomDated this 9 Day of June 1983

Issued

(Director)

NOTE: Section 64 of the Act provides that no change can be made to any building(s) or structures in connection with which this sewage system is installed. If the operation or effectiveness of the sewage system will be affected by the change, another application for a Certificate of Approval is obtained.

