



# HALIBURTON, KAWARTHA, PINE RIDGE DISTRICT HEALTH UNIT

## SEWAGE SYSTEM INSPECTION REPORT AND USE PERMIT

BV-5-91  
FILE NUMBER

### REPORT

INSTALLED BY: G. Shepherd

DATE May 24/91

Work authorized by certificate of approval has been satisfactorily completed and includes

Septic Tank/Holding Tank of working capacity of 3500 litres constructed of steel/concrete/fiberglass on site ☐ or prefabricated ☒  
to serve 4 bedrooms


Distribution Pipe: Type PVC ☒ Clay Tile ☐ Other ☐; Absorption Trench System ☐

Filter Bed System ☒ Filter Bed Area 32 sq. m. Contact Area 7 sq. m

Total 32 Lineal Metres in 7 runs of 4.5 metres and fed by gravity ☒ Siphon ☐ or Pump ☐

Other Details \_\_\_\_\_

Actual location and orientation of components of sewage system are as shown hereunder ☐ or as outlined on the Certificate of Approval form ☐



SCALE 1 square equals approx \_\_\_\_\_ metre.

The following work remains to be completed. Backfill system and sod or seed 2; Stabilize all sloped surfaces 8; Finish grading to shed run-off and divert water around leaching bed 4, Other \_\_\_\_\_

### USE PERMIT

Under section 67 of the Environmental Protection Act, 1980 and regulations and subject to the limitations thereof, a permit is hereby issued to

Ronald S Duncan

for the use and operation of the Class \_\_\_\_\_ Sewage System Installed/Altered under Certificate of Approval # \_\_\_\_\_

such system being located on Lot 4 Conc. \_\_\_\_\_ Plan 265 Sub. lot 373

Township/Municipality Berkley County Victoria

Inspected and Recommended by John McCallum

DATE May 24/91 Issued \_\_\_\_\_

(Director)

NOTE. Section 64 of the Act provides that no change can be made to any building(s) or structures in connection with which this sewage system is used, if the operation or effectiveness of the sewage system will be affected by the change, unless a Certificate of Approval is obtained.

