

SEWAGE SYSTEM INSPECTION REPORT AND USE PERMIT

S-69-82
FILE NUMBER


REPORT

DATE: June 7/83

INSTALLED BY: W. Downes

Work authorized by certificate of approval has been satisfactorily completed and includes:

- A. Septic Tank/Holding Tank of working capacity of _____ litres constructed of steel/concrete/fiberglass on site or prefabricated to serve _____ bedrooms
 - B. Distribution Pipe: Type - PVC , Clay Tile , Other _____; Absorption Trench System ; Filter Bed System ; Total 48 Linear Meters in VARIOUS LENGTHS runs of _____ m. and fed by gravity ; Syphon or Pump .
 - C. Other Details _____
- Actual location and orientation of components of sewage system are as shown hereunder or as outlined on the Certificate of Approval form



The following work remains to be completed: Backfill system and sod or seed ; Stabilize all sloped surfaces ; Finish grading to shed run-off and divert water around leaching bed ; Other _____

USE PERMIT

Under section 67 of the Environmental Protection Act, 1980 and regulations and subject to the limitations thereof, a permit is hereby issued to

ROSETA M. GIBSON

for the use and operation of the Class (1) TILED Sewage System installed/Altered under Certificate of Approval # _____

such system being located on Lot PT 12 Conc. _____ Plan 204 Sub. lot _____

Township/Municipality SOMERVILLE County VICTORIA

Inspected and Recommended by A. Blom

Dated this 2 Day of June 1983

Issued [Signature]
(Director)

NOTE: Section 64 of the Act provides that no change can be made to any building(s) or structures in connection with which this sewage system is _____ if the operation or effectiveness of the sewage system will be affected by the change, unless a Certificate of Approval is obtained.